

History

407
VF36DRHRH21044577
ECU configuration and services.
Test by ECU .
Engine / Gearbox.
Engine ECU.
HDI_SID803 RHR
Fault reading.

All the vehicle information

Vehicle : 407
Architecture : D2
VIN code : VF36DRHRH21044577
Motor : UNDEFINED
Chassis number or build code of the vehicle : 0
Body : BERLINE

Engine ECU

RECO_V4

Permanent fault. Pre/post heating relay circuit Relay not controlled and spark plugs supplied

Permanent fault. EGR solenoid valve Test of cleaning on switching off the ignition not correct

Permanent fault. Cooling circuit bypass valve solenoid valve circuit Short circuit between two wires or short circuit to positive (+)